



Great Lakes Diamond Aircraft Sales, Inc  
 9S070 Chandelle Drive  
 Naperville, IL 60564  
 800-962-9437  
[www.greatlakesdiamond.com](http://www.greatlakesdiamond.com)



## Specification Sheet

**MODEL:** HK36 Super Dimona TC100 **Engine:** Rotax 912 S3 Serial No. TBA  
**SERIAL NUMBER:** 36-846 **Prop:** MTV-21-A-C-F/CF 175-05 Serial No. TBA  
**REGISTRATION:** U.S. N391GL Special Registration number assigned

HK36 TC100 Standard Aircraft,	<b>\$ 177,457.40</b>
Garmin GTX 328 Mode S Transponder	Power Supply Socket for Hand-Helds GPS Access
Garmin SL40 COM	Lockable Side Windows
Compass	Rear Windows
Air Speed Indicator	Instrument Light and Map Light
Garmin GMA 1347 Digital Audio System	Three-wheel Landing Gear Absorbing Nose Wheel
Fuel Indicator	White Acrylic Paint
Tachometer	Winglets
Hobbs Meter	Tips on Horizontal Stabilizer
Oil Pressure Indicator	Registration Markings
Oil Temperature Indicator	Lockable Air Brakes
Cylinder Head Temperature Indicator	Wheel Fairings on Main and Nose Landing Gear
Ammeter	80 Lt tank
Two Individually Operated Disk Brakes	High Capacity Battery
4-point Safety Belts (all seats)	Noise Reduction Muffler
Adjustable Rudder Pedal	

### Options

PS Engineering PM 1000 II Intercom (with Headset Output)	\$ 727.04
Electric Club Vertical Speed Indicator	\$ 1,489.58
Preparation Installation Portable GPS	\$ 979.80
Folding Wings incl. Fittings	\$ 3,098.44
One man Rigging Kit for Folding Wings incl. Fittings	\$ 3,209.20
Landing Lights	\$ 2,137.10
Position Lights	\$ 1,251.02
Anti-collision Lights on Horizontal Stabilizer	\$ 1,874.40
External Power	\$ 985.48
Baggage Harness	\$ 323.76
Foldable sun Protection	\$ 752.60
Additional Generator	\$ 2,851.36
Upgrade to GTX330 Mode X Transponder	\$ 497.00
ELT Standard	\$ 497.00
Interior Trim - Premium Interior	\$ 5,576.34
Exterior Trim - Katana Xtreme - Red	\$ 1,659.98

<b>AIRCRAFT LIST PRICE</b>	<b>\$ 205,367.50</b>
<b>Shipping Charges</b>	<b>\$ 9,925.80</b>
<b>Total Price</b>	<b>\$ 215,293.30</b>

<b>US Customs</b>	<b>\$1,196.00</b>
<b>US Re-Assembly Charges</b>	<b>\$1,950.00</b>
<b>Documentation Fee</b>	<b>\$50.00</b>
<b>USD Total Price</b>	<b>\$ 218,489.30</b>



Great Lakes Diamond Aircraft Sales, Inc  
 9S070 Chandelle Drive  
 Naperville, IL 60564  
 800-962-9437  
[www.greatlakesdiamond.com](http://www.greatlakesdiamond.com)



## Specification Sheet

**MODEL:** HK36 Super Dimona TTC115 **Engine:** Rotax 914 F3 **Serial No.** TBA  
**SERIAL NUMBER:** 36-847 **Prop:** MTV-21-A-C-F/CF 175-05 **Serial No.** TBA  
**REGISTRATION:** U.S. N392GL Special Registration number assigned

HK36 TTC115 Standard Aircraft,	<b>\$ 190,663.40</b>
Garmin GTX 328 Mode S Transponder	Power Supply Socket for Hand-Helds GPS Access
Garmin SL40 COM	Lockable Side Windows
Compass	Rear Windows
Air Speed Indicator	Instrument Light and Map Light
Garmin GMA 1347 Digital Audio System	Three-wheel Landing Gear Absorbing Nose Wheel
Fuel Indicator	White Acrylic Paint
Tachometer	Winglets
Hobbs Meter	Tips on Horizontal Stabilizer
Oil Pressure Indicator	Registration Markings
Oil Temperature Indicator	Lockable Air Brakes
Cylinder Head Temperature Indicator	Wheel Fairings on Main and Nose Landing Gear
Ammeter	80 Lt tank
Two Individually Operated Disk Brakes	High Capacity Battery
4-point Safety Belts (all seats)	Noise Reduction Muffler
Adjustable Rudder Pedal	

### Options

PS Engineering PM 1000 II Intercom (with Headset Output)	\$ 727.04
Electric Club Vertical Speed Indicator	\$ 1,489.58
Preparation Installation Portable GPS	\$ 979.80
Folding Wings incl. Fittings	\$ 3,098.44
One man Rigging Kit for Folding Wings incl. Fittings	\$ 3,209.20
Landing Lights	\$ 2,137.10
Position Lights	\$ 1,251.02
Anti-collision Lights on Horizontal Stabilizer	\$ 1,874.40
External Power	\$ 985.48
Baggage Harness	\$ 323.76
Foldable sun Protection	\$ 752.60
Additional Generator	\$ 2,851.36
Upgrade to GTX330 Mode X Transponder	\$ 497.00
ELT Standard	\$ 497.00
Interior Trim - Premium Interior	\$ 5,576.34
Exterior Trim - Katana Xtreme - Red	<u>\$ 1,659.98</u>

<b>AIRCRAFT LIST PRICE</b>	<b>\$ 218,573.50</b>
<b>Shipping Charges</b>	<b>\$ 9,925.80</b>
<b>Total Price</b>	<b><u>\$ 228,499.30</u></b>

<b>US Customs</b>	<b>\$1,196.00</b>
<b>US Re-Assembly Charges</b>	<b>\$1,950.00</b>
<b>Documentation Fee</b>	<b>\$50.00</b>
<b>USD Total Price</b>	<b><u>\$ 231,695.30</u></b>